

CYPRES

Reliability

made in

Germany

HANDLING CYPRES 2 QUICK GUIDE

268,000 units

172 million jumps

more than

5200 lives saved

none have failed to

activate

and cut through the loop

when the conditions were met
to our current knowledge

Quick Guide

"Handling CYPRES 2"





click the button
(a short press and release)



press and hold down the button
(keep the button pressed)



release the button




next indication / action

indication sequence ends with




This Quick Guide does not replace the CYPRES 2 User's Guide nor releases the user from the obligation to comply with the contents of the CYPRES 2 User's Guide.

switching ON




self-test and
calibration



unit switched ON

unit information



PRESS and
 HOLD down

0'

00478

1. flight counter

78 145
ser no

2. serial number

09 20
next maint in

3. next maintenance date

F ft

4. scale feet or meter

A 0

5. user selected activation altitude

changeable MODE

Exp Stu Tan Spe

6. MODE

changeable MODE

Exp Spe

6. MODE

Exp Spe

SC 10

7. time duration for status change





0'

CYPRES



made in
Germany

Reliability


Dropzone Offset




set activation altitude



changing the scale



immediately !



changing the MODE



change-
able
MODE

Expert
Student
Tandem
Speed



Expert
Speed



Exp Stu Tan Spe



PRESS and
HOLD down



immediately !



Exp Stu Tan Spe



2x

